


[Dec 07, 2022 Fully Updated Dumps PDF - Latest HQT-4180 Exam Questions and Answers [Q13-Q31]



[Dec 07, 2022] Fully Updated Dumps PDF - Latest HQT-4180 Exam Questions and Answers [Q13-Q31]

[Dec 07, 2022] Fully Updated Dumps PDF - Latest HQT-4180 Exam Questions and Answers
100% Free HQT-4180 Exam Dumps to Pass Exam Easily from BraindumpsIT

Q13. What is the maximum size of a basic volume carved out from an internal parity group on a VSP E590 system?

- * 1 TB
- * 2.99 TB
- * 65 TB
- * 128 TB

Q14. A customer wants to change a production RAID Group from RAID 5 (7D+1P) to RAID 6 (6D + 2P) on a VSP G700 during normal operations. They have just unmapped the LUNs from the channel ports.

What needs to be performed next?

- * The RAID level must be changed in Storage Navigator.
- * The RAID level must be changed in the SVP Maintenance window.
- * The RAID 5 Group must be put into DRU mode in Storage Navigator.
- * The RAID Group must be deleted.

Q15. A drive in a 3D + 1P RAID group fails in a VSP G700 and there is no spare drive available.

Which two actions are automatically performed by the system? (Choose two.)

- * An alert is generated.
- * Dynamic Sparing is started.
- * The Correction Copy process starts.
- * The RAID group is placed in Correction Access.

Q16. What is the recommended RAID level when creating a Hitachi Dynamic Provisioning (HDP) pool?

- * RAID 1
- * RAID 1+0
- * RAID 5
- * RAID 6

Q17. A customer wants to upgrade their VSP E790 with a SAS Expansion feature.

What are three requirements? (Choose three.)

- * Two additional Disk Boards (DKBs) have to be installed.
- * Slots B of both controllers must be available for DKB installation.
- * The SAS Expansion license has to be installed.
- * In Shared Memory, the Extension1 has to be enabled.
- * Drive Boxes (DBs) with SAS interface have to be added.

Q18. Your customer wants to connect multiple servers to a new port on a VSP G700. The correct topology has already been set for the port.

What should you do next?

- * Enable Port Security.
- * Enable Host Group security.
- * Create a Host Group.
- * Scan for all WWNs.

Q19. One Unix server and one Windows server share the front-end ports CL1-A and CL2-A of a VSP E590 system.

What are two requirements to separate the I/Os of the servers? (Choose two.)

- * Both servers must be registered in two different Host Groups.
- * Port security must be enabled on both ports.
- * The Universal Volume Manager license must be installed.
- * Two cache partitions must be created on the VSP for the servers.

Q20. You need to replace a failing power supply (PS) in a VSP E590.

What is the correct procedure?

- * Check if the status of the PS is blocked, and if yes, then replace it directly.
- * Use the Maintenance Utility for blocking the PS, then replace it.
- * Use the Maintenance Utility for blocking the controller, then replace the PS.
- * Use the MPC for blocking the PS, then replace it.

Q21. What are two functions of the LAN Blade in the VSP Midrange family? (Choose two.)

- * It provides the LAN connection to the file module.
- * It provides the maintenance port connecting to the MPC.
- * It provides the iSCSI connection to the servers.
- * It provides the management port connecting to the customer LAN.

Q22. Which two tools are available to configure NTP server settings on a VSP E590 system? (Choose two.)

- * Storage Navigator
- * Maintenance Utility
- * Initial Setup Wizard
- * HSA Embedded

Q23. Which two actions can be performed with Hitachi Ops Center Administrator? (Choose two.)

- * Perform Self-Service Maintenance.
- * Manage virtual storage machines.
- * Manage multiple VSP Midrange storage systems.
- * Configure the Hitachi Remote Ops Monitor Agent.

Q24. A customer has a VSP G370 with the encryption license key installed. They now want to have all the DP-Volumes of a certain pool located on encrypted RAID Groups.

What are two requirements? (Choose two.)

- * The controller board must support encryption.
- * The RAID level of RAID Groups in the pool must be RAID 6.
- * At least 20 GB of Shared Memory must be installed.
- * The RAID Groups in the pool must be formatted with encryption enabled.

Q25. You need to replace a broken fan in a VSP E1090.

What is the correct procedure?

- * Use the MPC for blocking the fan, then replace it.
- * Use the Maintenance Utility for stopping the fan, then replace it.
- * Remove the broken fan, then replace it.
- * Use Storage Navigator for blocking the fan, then replace it.

Q26. Which three RAID configurations are supported by VSP Midrange systems? (Choose three.)

- * 2D + 2D
- * 4D + 1P
- * 7D + 1P
- * 8D + 1P
- * 10D + 2P

Free HQT-4180 Exam Questions HQT-4180 Actual Free Exam Questions:

https://www.braindumpsit.com/HQT-4180_real-exam.html